







# US MOTOR WIRINGS



HIGH VOLTAGE



LOW VOLTAGE

